



Do not enter the marked area.

Do not move vehicles or equipment through the walk zone.

Report to the Walk Leader if you must cross the area.

Watch for personnel scanning the ground.



Clean your work area continuously during the task.

Do not leave debris to accumulate.

Place waste in the nearest FOD container immediately.

If you see safe debris, pick it up, even if it is not yours.

A clean area is a safe area.



Before you leave, check your work area.

Tools returned to shadow board?

Consumables counted?

Debris removed?

Area ready for the next person?

If something is missing, report it immediately.